




Denna handling är vår egendom och får ej utan vårt skriftliga medgivande kopieras, förevisas eller överlämnas till obehörig person



Rev.	Qty.	Change	Date	Sign.
A	3	R1 ->R2. R30 ->R15. A wider flange on the bowls that counteracts shrinkage stress during welding. Adaptation in the bowls flange for the tap hole to make the tap sit more firmly.	2022-01-21	MR
B	1	Overflow changed from left to right bowl to harmonize with Horizon.	2022-10-17	LC
C	3	Flatness tolerance 1,5 added. Tolerance (±1) added.	2022-11-23	LC
D	4	Dimensions changed from 815 -> 820, 510 -> 515, 8 -> 9, 47.5 -> 50, 45 -> 47.5. New tolerance.	2023-01-10	LC
E	4	Dimensions changed from 9 -> 9.5, 57 -> 59,50. New design of rails.	2023-01-31	LC
F	1	New name from Nivis 815DF -> Nivis 82DF because of dimension change.	2023-02-27	LC



Nr.	ANT.	Name	Material	Art. nr
1	1	Bänklplan Nivis815DF	1.4301	ZPNIV815DF
2	2	Klammerskena (gavel)	Aluminium EN 6060	750521
3	2	Klammerskena (långsida)	Aluminium EN 6060	750524
4	1	14808 345-Fläns Nivis	EN 1.4301	
5	1	14808 345-Breddavlopp Rektangulärt Fläns HZevo	EN 1.4301	

Konstr.	LC	Ritad	LC	Godk.	MR	Smst nr.	Ers.		
Dat.	2021-08-17	Skala	1:5			Intra Nivis 82DF Art.no: XNIV82DF		Ritn.nr	15815
intra SCANDINAVIAN DESIGN									Ändr. F

